

This firmware package (C3414-500-S02J2) contains a 6.9.4.4 revision vxWorks operating system image that utilizes **OpenSSL 1.0.1k revision**.

This vxWorks image must be installed into the RTU to make use of the features in the updated OpenSSL code.